

# Orange County Department of Health Division of Environmental Health

## Coliform samples collected by OCDOH

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>
<b>NY3530168</b>	<b>2727 ROUTE 94</b>	<b>BLOOMING GROVE (T)</b>			
	Basement tap	3/12/2018	RT	ABS	1.3
<b>NY3516940</b>	<b>ALL SEASONS CO OP HOMES</b>	<b>MONROE (T)</b>			
	114 Scott St. Kitchen	3/12/2018	RT	ABS	0.5
<b>NY3503588</b>	<b>ARLUCK WATER DISTRICT</b>	<b>WAWAYANDA (T)</b>			
	22 Seth Drive outside tap	1/10/2018	RT	ABS	1.6
	22 Seth Drive outside tap	2/14/2018	RT	ABS	0.7
	22 Seth Drive outside tap	3/5/2018	RT	ABS	1.2
	22 Seth Drive outside tap	4/9/2018	RT	ABS	2.2
<b>NY3503536</b>	<b>ARROW PARK INC.</b>	<b>MONROE (T)</b>			
	1089 Orange Turnpike basement sink	1/23/2018	RT	ABS	1.7
	1089 Orange Turnpike basement sink	2/13/2018	RT	ABS	0.4
	1089 Orange Turnpike basement sink	3/27/2018	RT	ABS	1
<b>NY3503550</b>	<b>BEAVER DAM LAKE WATER CORP.</b>	<b>NEW WINDSOR (T)</b>			
	528 Shore Drive kitchen tap	1/24/2018	RT	ABS	1.2
	303 Hickory Avenue kitchen	2/27/2018	RT	ABS	0.5
	303 Hickory Avenue kitchen	3/14/2018	RT	ABS	0.6
	307 Hickory Ave. kitchen	4/18/2018	RT	ABS	0.5
<b>NY3501331</b>	<b>BEL-AIR TRAILER PARK</b>	<b>MONTGOMERY (T)</b>			
	Treatment building tank tap	1/2/2018	RT	ABS	0.8
	Wellhouse tank tap	2/5/2018	RT	ABS	0.5
	Well house tank tap	3/5/2018	RT	ABS	0.4
	Well house tank tap	4/3/2018	RT	ABS	0.4

**Orange County Department of Health  
Division of Environmental Health**

**Coliform samples collected by OCDOH**

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>	
<b>NY3503889</b>	<b>BELVALE COMMUNITY</b>	<b>CHESTER (T)</b>				
	Reception Office bathroom handsink tap	1/16/2018	RT	ABS	0.5	
	Reception bathroom handsink tap	2/14/2018	RT	ABS	0.5	
	Reception Office bathroom handsink tap	3/19/2018	RT	ABS	0.4	
	Reception Office bathroom handsink tap	4/11/2018	RT	ABS	0.7	
<b>NY3503602</b>	<b>BELVALE PARK W.D.</b>	<b>WARWICK (T)</b>				
	Treatment building entry point tap	2/6/2018	RT	ABS	1.8	
	Treatment building entry point tap	4/4/2018	RT	ABS	1.6	
<b>NY3510816</b>	<b>BIG SKY II, LLC</b>	<b>WALLKILL (T)</b>				
	Treatment room entry point tap	2/13/2018	RT	ABS	1.2	
	Treatment room entry point tap	3/5/2018	RT	PRES	ABS	0.1
	Treatment room entry point tap	4/2/2018	RT	ABS	3.8	
<b>NY3503620</b>	<b>BLOOMING GROVE WD #2-OXFORD HE</b>	<b>BLOOMING GROVE (T)</b>				
	4 Seely Road outside tap	1/10/2018	RT	ABS	3.5	
	4 Seely Road outside tap	2/21/2018	RT	ABS	3.2	
	4 Seely Road outside tap	3/6/2018	RT	ABS	1.2	
	4 Seely Road outside tap	4/4/2018	RT	ABS	1.2	
<b>NY3503595</b>	<b>BLOOMING GROVE WD #3-TOMAHAWK</b>	<b>BLOOMING GROVE (T)</b>				
	Sayer Road surveillance tap	1/22/2018	RT	ABS	1	
	Sayer Road surveillance tap	2/26/2018	RT	ABS	1.5	
	Sayer Road surveillance tap	3/27/2018	RT	ABS	1	
	Sayer road surveillance tap	4/17/2018	RT	ABS	1.3	

# Orange County Department of Health Division of Environmental Health

## Coliform samples collected by OCDOH

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>
<b>NY3503625</b>	<b>BLOOMING GROVE WD #4-TAPPAN HO</b>	<b>BLOOMING GROVE (T)</b>			
	116 Barnes Road kitchen	1/3/2018	RT	ABS	1
	116 Barnes Road kitchen	2/13/2018	RT	ABS	0.1
	106 Barnes Road kitchen	2/13/2018	RT	ABS	0 T
	112 Barnes Road kitchen	3/19/2018	RT	ABS	0 T
	116 Barnes Road kitchen	3/19/2018	RT	ABS	0.8
	90 Barnes Road kitchen - sample 2	3/19/2018	RT	ABS	0 T
	116 Barnes Road kitchen	4/4/2018	RT	ABS	0.3
<b>NY3503591</b>	<b>BLOOMING GROVE WD #5-MT. VIEW</b>	<b>BLOOMING GROVE (T)</b>			
	Thompson downstairs bathroom	1/10/2018	RT	ABS	0.9
	Adelaide Lane surveillance tap	2/20/2018	RT	ABS	1
	Adelaide Lane surveillance tap	3/27/2018	RT	ABS	0.3
	Adelaide Lane surveillance tap	4/9/2018	RT	ABS	0.3
<b>NY3512132</b>	<b>BLUE LAKE</b>	<b>WARWICK (T)</b>			
	The Woodlands Clubhouse men's room	1/16/2018	RT	ABS	0.4
<b>NY3505661</b>	<b>BRAESIDE AQUA CORPORATION</b>	<b>BLOOMING GROVE (T)</b>			
	31 Evergreen Drive kitchen	1/8/2018	RT	ABS	0.3
	56 Hilltop Drive kitchen	1/8/2018	RT	ABS	0.3
	31 Evergreen Drive kitchen	2/20/2018	RT	ABS	0.5
	10 Ludwig Drive kitchen	2/20/2018	RT	ABS	0.3
	31 Evergreen Drive kitchen tap	3/27/2018	RT	ABS	0.5
	56 Hillside Drive kitchen sink	3/27/2018	RT	ABS	0.5
	56 Hilltop Drive kitchen	4/9/2018	RT	ABS	0.4
	31 Evergreen kitchen tap	4/9/2018	RT	ABS	0.4

# Orange County Department of Health Division of Environmental Health

## Coliform samples collected by OCDOH

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>	
<b>NY3501332</b>	<b>BRITTANY TERRACE</b>	<b>NEW WINDSOR (T)</b>				
	Model Home kitchen tap	1/24/2018	RT	ABS	1	
	Lot #305 kitchen tap	2/21/2018	RT	ABS	0.8	
	Lot #101 kitchen	3/26/2018	RT	ABS	0.9	
	Office front yard tap	4/18/2018	RT	ABS	0.7	
<b>NY3530056</b>	<b>CAMPBELL HALL APARTMENTS</b>	<b>HAMPTONBURGH (T)</b>				
	Apt. #3 kitchen	1/3/2018	RT	ABS	1.3 T	
	Laundry room sink	2/13/2018	RT	ABS	0.8	
	Apt. #2 kitchen	3/12/2018	RT	ABS	0.9	
	Apt. #10 kitchen	4/4/2018	RT	ABS	2	
<b>NY3510479</b>	<b>CAMPBELL HALL REHABILITATION CENTER</b>	<b>HAMPTONBURGH (T)</b>				
	Lobby men's room	1/29/2018	RT	ABS	1.3	
	Lobby men's room	2/28/2018	RT	ABS	1.2	
	Lobby men's room sink	3/28/2018	RT	ABS	1.4	
<b>NY3501335</b>	<b>CANDLESTICK PARK</b>	<b>NEWBURGH (T)</b>				
	Lot #8 kitchen	1/10/2018	RT	ABS	0.5	
	Lot #99 kitchen	2/28/2018	RT	ABS	0.4	
	Lot #99 kitchen sink	3/20/2018	RT	ABS	0.5	
	Lot #99 kitchen	4/11/2018	RT	ABS	0.5	
<b>NY3501336</b>	<b>CASTLE HIGH TRAILER PARK</b>	<b>GREENVILLE (T)</b>				
	77 Stern Scenic Dr. bathroom handsink tap	1/23/2018	RT	ABS	0.3	
	77 Stern Scenic Dr. bathroom handsink tap	2/21/2018	RT	ABS	0.3	
	77 Stern Scenic Drive bathroom handsink ta	3/14/2018	RT	ABS	1.6	
	79 Stern Scenic Drive kitchen tap	4/11/2018	RT	ABS	1.4	

# Orange County Department of Health Division of Environmental Health

## Coliform samples collected by OCDOH

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>	
<b>NY3503524</b>	<b>CHESTER VILLAGE</b>	<b>CHESTER (V)</b>				
	Shop Rite men's bathroom left handsink tap	2/14/2018	RT	ABS	0.9	
<b>NY3530177</b>	<b>CORBIN HILLS WATER SUPPLY</b>	<b>HIGHLANDS (T)</b>				
	Unit 6 kitchen	1/9/2018	RT	ABS	0.7	
<b>NY3503526</b>	<b>CORNWALL-ON-HUDSON</b>	<b>CORNWALL-ON-HUDSON (V)</b>				
	Village Hall restroom sink	3/14/2018	RT	ABS	0.9	
<b>NY3530071</b>	<b>COUNTRY CROSSING</b>	<b>WOODBURY (T)</b>				
	44 Country Hollow kitchen sink	1/22/2018	RT	ABS	0.4	
	Country Hollow kitchen tap	2/26/2018	RT	PRES	ABS	1.4
	Sequoia Trail downstairs bathroom	2/28/2018	RP	ABS	1	
	38 Country Crossing	2/28/2018	RP	ABS	0.8	
	6 Country Holo99w kitchen tap	2/28/2018	RP	PRES	ABS	1.3
	6 Country Hollow kitchen	3/19/2018	RT	ABS	1	
	21 Country Hollow garage sink	4/18/2018	RT	ABS	0.8	
<b>NY3520965</b>	<b>CROMWELL HILL COMMONS</b>	<b>MONROE (T)</b>				
	Club house men's room	1/23/2018	RT	ABS	0.6	
	Clubhouse pool side tap	2/27/2018	RT	ABS	0.7	
	Community Building pool side tap	3/27/2018	RT	ABS	0.8	
	Community Building men's room sink	4/4/2018	RT	ABS	0.4	

**Orange County Department of Health  
Division of Environmental Health**

**Coliform samples collected by OCDOH**

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>
<b>NY3503577</b>	<b>DEERPARK MANOR</b>	<b>DEERPARK (T)</b>			
	32 Apple Lane outside tap	1/22/2018	RT	ABS	0.5
	32 Apple Lane outside tap	1/22/2018	RT	ABS	0.5
	9 Oak Circle kitchen tap	2/20/2018	RT	ABS	0.3
	9 Oak Circle kitchen tap	2/20/2018	RT	ABS	0.3
	32 Apple Lane outside tap	3/14/2018	RT	ABS	0.2
	32 Apple Lane outside tap	3/14/2018	RT	ABS	0.2
	32 Apple Lane outside tap	4/9/2018	RT	ABS	0.7
	32 Apple Lane outside tap	4/9/2018	RT	ABS	0.7
<b>NY3510309</b>	<b>DELANO COTTAGES</b>	<b>BLOOMING GROVE (T)</b>			
	Treatment shed tank tap	3/19/2018	RT	ABS	0.4
<b>NY3503568</b>	<b>DENTON HILLS WATER DISTRICT</b>	<b>WAWAYANDA (T)</b>			
	389 Greeves Road outside tap	1/10/2018	RT	ABS	0.2
	389 Greeves Road outside tap	2/14/2018	RT	ABS	1.6
	389 Greeves Road outside tap	3/14/2018	RT	ABS	1.8
	389 Greeves Road outside tap	4/9/2018	RT	ABS	1.8
<b>NY3530193</b>	<b>DEVANS GATE SENIOR HOUSING</b>	<b>MOUNT HOPE (T)</b>			
	Phase II laundry room utility sink tap	1/3/2018	RT	ABS	0.5
	Phase II laundry room utility sink tap	2/20/2018	RT	ABS	0.3
	Phase II laundry room utility sink tap	3/14/2018	RT	ABS	0.2
	Phase II laundry room utility sink tap	4/2/2018	RT	ABS	0.1
<b>NY3511323</b>	<b>DONOVANS PLACE</b>	<b>CRAWFORD (T)</b>			
	Cabin #11 kitchen	3/5/2018	RT	ABS	1.5

**Orange County Department of Health  
Division of Environmental Health**

**Coliform samples collected by OCDOH**

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>
<b>NY3530183</b>	<b>DRAGON SPRINGS</b>	<b>DEERPARK (T)</b>			
	Welcome Center kitchen tap	1/8/2018	RT	ABS	0.2
	Welcome Center kitchen tap	2/20/2018	RT	ABS	0.2
	Welcome Center kitchen tap	3/14/2018	RT	ABS	0.2
	Welcome Center kitchen tap	4/10/2018	RT	ABS	0.3
<b>NY3505664</b>	<b>EURICH HEIGHTS</b>	<b>WARWICK (T)</b>			
	Antiques & Flowers bathroom utility sink tap	1/16/2018	RT	ABS	0.7
	Treatment Building entry point tap	2/21/2018	RT	ABS	0.7
	Treatment building entry point tap	3/13/2018	RT	ABS	0.5
	Antiques & Flowers bathroom utility sink tap	4/4/2018	RT	ABS	0.7
<b>NY3501329</b>	<b>FAIRLAWN MOBILE VILLAGE</b>	<b>DEERPARK (T)</b>			
	Office outside tap	1/8/2018	RT	ABS	0.3
	Office kitchen tap	2/13/2018	RT	ABS	0.3
	Office kitchen tap	3/5/2018	RT	ABS	0.2
	Office outside tap	4/9/2018	RT	ABS	0.3
<b>NY3517527</b>	<b>FEDERAL CORRECTIONAL INST.</b>	<b>OTISVILLE (V)</b>			
	Main lobby staff bathroom handsink tap	1/8/2018	RT	ABS	0.9
	Main Lobby staff bathroom handsink tap	4/2/2018	RT	ABS	1.4

# Orange County Department of Health Division of Environmental Health

## Coliform samples collected by OCDOH

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>	
<b>NY3530191</b>	<b>FIELD CREST</b>	<b>CHESTER (T)</b>				
	41 Rebecca Road basement kitchen tap	1/16/2018	RT	ABS	0.5	
	41 Rebecca Road main level kitchen tap	2/14/2018	RT	ABS	0.2	
	41 Rebecca Road main level kitchen tap	3/19/2018	RT	PRES	ABS	0.5
	119 Nancy Lane bathroom handsink tap	3/22/2018	RP	ABS	0.3	
	32 Rebecca Road kitchen tap	3/22/2018	RP	ABS	0.2	
	41 Rebecca Road outside tap	3/22/2018	RP	ABS	0.3	
	41 Rebecca Road outside tap	4/11/2018	RT	ABS	0.3	
<b>NY3503615</b>	<b>FIRTHCLIFFE W.D.</b>	<b>CORNWALL (T)</b>				
	Bigg's Quality Auto Repair breakroom sink	1/9/2018	RT	ABS	1	
	Bigg's Quality Auto Repair breakroom sink	1/9/2018	RT	ABS	1	
	Bigg's Quality Auto Repari breakroom sink	2/6/2018	RT	ABS	1.2	
	Bigg's Quality Auto Repari breakroom sink	2/6/2018	RT	ABS	1.2	
	Bigg's Quality Auto Repair breakroom sink	3/26/2018	RT	ABS	1	
	Bigg's Quality Auto Repair breakroom sink	3/26/2018	RT	ABS	1	
	Bigg's Quality Auto Repair	4/10/2018	RT	ABS	1	
	Bigg's Quality Auto Repair	4/10/2018	RT	ABS	1	
<b>NY3503527</b>	<b>FLORIDA VILLAGE</b>	<b>FLORIDA (V)</b>				
	Dunkin Donuts men's bathroom hand sink tap	1/2/2018	RT	ABS	0.3	
	Stop & Wash utility sink tap	4/4/2018	RT	ABS	1.2	
<b>NY3530190</b>	<b>FOX HILL COMMUNITY</b>	<b>MONTGOMERY (T)</b>				
	Utility building sink	1/23/2018	RT	ABS	0.9	
	Utility building	2/26/2018	RT	ABS	0.6	
	Utility building sink	3/19/2018	RT	ABS	0.2	
	Utility building sink	4/16/2018	RT	ABS	0.8	



# Orange County Department of Health Division of Environmental Health

## Coliform samples collected by OCDOH

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>	
<b>NY3530030</b>	<b>FREEHILL WATER SUPPLY</b>	<b>GREENVILLE (T)</b>				
	Building #23 outside tap	3/26/2018	RT	ABS	0.7	
<b>NY3517981</b>	<b>GILLEN TRAILER PARK</b>	<b>WALLKILL (T)</b>				
	735 Dosen Road Lot #1 kitchen tap	3/19/2018	RT	ABS	0.3	
<b>NY3503528</b>	<b>GOSHEN VILLAGE</b>	<b>GOSHEN (V)</b>				
	Burger King men's bathroom handsink tap	1/10/2018	RT	ABS	2.2	
<b>NY3503529</b>	<b>GOSHEN W.D. #1 (HAMBLETONIAN PARK)</b>	<b>GOSHEN (T)</b>				
	Sewer Station outside tap	1/23/2018	RT	ABS	0.2	
	Sewer Station outside tap	2/14/2018	RT	ABS	0.5	
	Sewer Station outside tap	3/5/2018	RT	ABS	0.2	
	Sewer station outside tap	4/11/2018	RT	ABS	0.2	
<b>NY3503605</b>	<b>GOSHEN W.D. #2 (ARCADIA HILLS)</b>	<b>GOSHEN (T)</b>				
	2 Greenwood Drive main floor bathroom handsink tap	1/16/2018	RT	ABS	1.2	
	18 Larchwood Drive outside tap	2/26/2018	RT	ABS	1.4	
	2 Greenwood Drive main floor bathroom hand sink tap	3/20/2018	RT	ABS	1.5	
	18 Larchwood Drive outside tap	4/10/2018	RT	ABS	1.4	
<b>NY3510680</b>	<b>GREEN ACRES PARK</b>	<b>GREENVILLE (T)</b>				
	9 Trails End kitchen tap	1/22/2018	RT	ABS	0.7	
	9 Trails End kitchen tap	2/21/2018	RT	ABS	0.3	
	8 Trails End kitchen tap	3/14/2018	RT	ABS	0.7	
	9 Trails End kitchen tap	4/11/2018	RT	ABS	0.5	
<b>NY3503530</b>	<b>GREENWOOD LAKE VILLAGE</b>	<b>GREENWOOD LAKE</b>				
	Subway bathroom hand sink tap	1/2/2018	RT	ABS	0.3	

**Orange County Department of Health  
Division of Environmental Health**

**Coliform samples collected by OCDOH**

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>
<b>NY3501324</b>	<b>GREENWOOD MOBILE HOME COURT</b>	<b>DEERPARK (T)</b>			
	6 Fawn Hill bathroom hand sink tap	1/22/2018	RT	ABS	0.3
	6 Fawn Hill bathroom handsink tap	2/20/2018	RT	ABS	
	6 Fawn Hill bathroom handsink tap	3/26/2018	RT	ABS	0.3
	1 Pheasant Hill kitchen tap	4/10/2018	RT	ABS	0.3
<b>NY3503531</b>	<b>HARRIMAN VILLAGE</b>	<b>HARRIMAN (V)</b>			
	Village of Harriman Hall restroom tap	3/27/2018	RT	ABS	0.4
<b>NY3530122</b>	<b>HEARTHSTONE MANOR</b>	<b>GOSHEN (T)</b>			
	Community Room kitchen tap	1/10/2018	RT	ABS	0.2
	Community Room kitchen tap	1/10/2018	RT	ABS	0.2
	Community Room kitchen tap	2/21/2018	RT	ABS	0.5
	Community Room kitchen tap	2/21/2018	RT	ABS	0.5
	Community Room kitchen tap	3/13/2018	RT	ABS	0.5
	Community Room kitchen tap	3/13/2018	RT	ABS	0.5
	Laundry room utility sink tap	4/4/2018	RT	ABS	0.7
	Laundry room utility sink tap	4/4/2018	RT	ABS	0.7
<b>NY3503606</b>	<b>HIDDEN VALLEY ESTATES</b>	<b>MOUNT HOPE (T)</b>			
	19 Wedgewood Lane kitchen tap	1/8/2018	RT	ABS	0.7
	19 Wedgewood Lane kitchen tap	2/20/2018	RT	ABS	0.9
	19 Wedgewood Lane outside tap	3/14/2018	RT	ABS	0.7
	19 Wedgewood Lane kitchen tap	4/10/2018	RT	ABS	0.7
<b>NY3503532</b>	<b>HIGHLAND FALLS VILLAGE</b>	<b>HIGHLAND FALLS (V)</b>			
	Library men's room	1/9/2018	RT	ABS	0.8

# Orange County Department of Health Division of Environmental Health

## Coliform samples collected by OCDOH

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>	
<b>NY3530057</b>	<b>HIGHLANDS WATER DISTRICT</b>	<b>HIGHLANDS (T)</b>				
	Holiday Inn lobby men's room	3/26/2018	RT	ABS	0.5	
<b>NY3501325</b>	<b>HILL N DALE TRAILER PARK</b>	<b>NEW WINDSOR (T)</b>				
	Lot #27 kitchen	1/2/2018	RT	ABS	1.3	
	Lot #24 kitchen tap	2/5/2018	RT	ABS	0.9	
	Lot #12 kitchen tap	3/5/2018	RT	ABS	1.4	
	Lot #12 kitchen	4/3/2018	RT	ABS	1.1	
<b>NY3513623</b>	<b>HILLTOP HAVEN TRAILER PARK</b>	<b>NEWBURGH (T)</b>				
	Hilltop Haven TP well house tap	3/20/2018	RT	ABS	0.4	
<b>NY3513655</b>	<b>HOGENCAMP TRAILER PARK</b>	<b>WAWAYANDA (T)</b>				
	Treatment building entry point tap	3/22/2018	RT	ABS	2.2	
<b>NY3501326</b>	<b>HOLIDAY MOBILE PARK INC.</b>	<b>MONTGOMERY (T)</b>				
	376 Kipling Road kitchen sink	1/2/2018	RT	ABS	0.5	
	376 Kipling Road kitchen tap	2/5/2018	RT	PRES	ABS	2.5
	376 Kipling Lane kitchen tap	3/5/2018	RT	ABS	1.5	
	376 Kipling Road kitchen tap	4/3/2018	RT	ABS	0.8	
<b>NY3501327</b>	<b>HUGUENOT ESTATES EAST</b>	<b>DEERPARK (T)</b>				
	22 Daisy Drive kitchen tap	1/8/2018	RT	ABS	0.7	
	Office bathroom handsink tap	2/20/2018	RT	ABS	0.7	
	Office bathroom hand sink tap	3/14/2018	RT	ABS	1.5	
	11 Cherry St. kitchen tap	4/9/2018	RT	ABS	0.7	
	Treatment building well I#2 raw water tap	4/18/2018	RT	ABS		

# Orange County Department of Health Division of Environmental Health

## Coliform samples collected by OCDOH

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>	
<b>NY3503638</b>	<b>HYNDMAN HEIGHTS W.D.</b>	<b>MONTGOMERY (T)</b>				
	Bone'z garage shop sink	1/2/2018	RT	ABS	0.1	
	Bonez garage shop sink	2/5/2018	RT	ABS	0.4	
	Bonez garage shop sink	3/5/2018	RT	ABS	0.5	
	Bone'z garage shop sink	4/3/2018	RT	ABS	0.4	
<b>NY3503592</b>	<b>INDIAN KILL</b>	<b>TUXEDO (T)</b>				
	SF Building 1st floor men's room	3/6/2018	RT	ABS	1.7	
<b>NY3530069</b>	<b>JBC RENTAL PROPERTIES, LLC.</b>	<b>WAWAYANDA (T)</b>				
	Treatment room entry point tap	3/26/2018	RT	ABS	0.2	
<b>NY3510136</b>	<b>JZM L.L.C.</b>	<b>WALLKILL (T)</b>				
	Building #5 basement tap	1/3/2018	RT	ABS	1.6	
	Building #7 utility room tap	2/13/2018	RT	ABS	0.3	
	Building #5 basement tap	3/5/2018	RT	ABS	1.5	
	Building #7 utility room tap	4/2/2018	RT	ABS	1.2	
<b>NY3503598</b>	<b>KING TRACT</b>	<b>CHESTER (T)</b>				
	6 Townsend Pl. outside tap	1/16/2018	RT	ABS	0.2	
	22 Able Noble Dr. basement bathroom handsink tap	2/26/2018	RT	ABS	1.2	
	16 Able Noble Drive kitchen tap	3/20/2018	RT	ABS	0.9	
	22 Able Noble Drive basement bathroom handsink tap	4/9/2018	RT	ABS	0.5	
<b>NY3521334</b>	<b>KINGS ESTATES</b>	<b>WARWICK (T)</b>				
	94 Marian Court kitchen tap	3/20/2018	RT	ABS	0.7	
<b>NY3503627</b>	<b>KIRYAS JOEL VILLAGE</b>	<b>KIRYAS JOEL (V)</b>				
	Dairy restaurant customer handwash	2/26/2018	RT	ABS	1.2	
	Dairy restaurant customer handwash	2/26/2018	RT	ABS	1.2	

**Orange County Department of Health  
Division of Environmental Health**

**Coliform samples collected by OCDOH**

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>	
<b>NY3503563</b>	<b>KNOLLS WATER CO., INC.</b>	<b>WARWICK (T)</b>				
	25 Cliff Road kitchen tap	1/16/2018	RT	ABS	0.7	
	25 Cliff Road kitchen tap	1/16/2018	RT	ABS	0.7	
	39 Cliff Road kitchen tap	2/26/2018	RT	ABS	1.8	
	39 Cliff Road kitchen tap	2/26/2018	RT	ABS	1.8	
	38 Cliff Road kitchen tap	3/20/2018	RT	ABS	1.4	
	38 Cliff Road kitchen tap	3/20/2018	RT	ABS	1.4	
	39 Cliff Road kitchen tap	4/9/2018	RT	ABS	1.2	
	39 Cliff Road kitchen tap	4/9/2018	RT	ABS	1.2	
<b>NY3505650</b>	<b>LAKE HILL FARMS WATER DISTRICT</b>	<b>CHESTER (T)</b>				
	5 Grant Drive kitchen tap	3/20/2018	RT	ABS	5	
<b>NY3503544</b>	<b>LAKE VUE PARK W.D.</b>	<b>MONTGOMERY (T)</b>				
	356 Lake Vue Drive downstairs bathroom	1/16/2018	RT	ABS	0.3	
	318 Lake Vue Drive kitchen	2/14/2018	RT	ABS	0.3	
	316 Lake Vue Drive laundry room sink	3/26/2018	RT	ABS	0.4	
<b>NY3530051</b>	<b>LAKWOOD ESTATES</b>	<b>DEERPARK (T)</b>				
	4 Forrest bathroom left hand sink tap	1/8/2018	RT	ABS	0.7	
	4 Forrest kitchen tap	2/13/2018	RT	ABS	0.7	
	4 Forrest kitchen tap	3/14/2018	RT	ABS	0.7	
	4 Forrest kitchen tap	4/9/2018	RT	ABS	0.7	
<b>NY3503033</b>	<b>LAMPLIGHT VILLAGE</b>	<b>MONROE (T)</b>				
	Building #4 laundry room sink	1/23/2018	RT	ABS	0.9	
	Building #4 laundry room sink	2/26/2018	RT	ABS	0.5	
	Building #4 laundry room sink	3/19/2018	RT	ABS	0.5	
	Building #4 laundry room sink	4/17/2018	RT	ABS	0.7	

**Orange County Department of Health  
Division of Environmental Health**

**Coliform samples collected by OCDOH**

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>
<b>NY3510368</b>	<b>LINDSAY TRAILER PARK</b>	<b>WALLKILL (T)</b>			
	Trailer #8 kitchen tap	3/26/2018	RT	ABS	0.1
<b>NY3503585</b>	<b>LORELEI WATER SUPPLY</b>	<b>WALLKILL (T)</b>			
	15 Lorelei Drive kitchen tap	1/16/2018	RT	ABS	0.7
	15 Lorelei Drive kitchen tap	1/16/2018	RT	ABS	0.7
	15 Lorelei Drive kitchen tap	2/21/2018	RT	ABS	0.9
	15 Lorelei Drive kitchen tap	2/21/2018	RT	ABS	0.9
	15 Lorelei Drive kitchen tap	3/22/2018	RT	ABS	1.2
	15 Lorelei Drive kitchen tap	3/22/2018	RT	ABS	1.2
	15 Lorelei Drive kitchen tap	4/10/2018	RT	ABS	0.3
	15 Lorelei Drive kitchen tap	4/10/2018	RT	ABS	0.3
<b>NY3530065</b>	<b>MANSION RIDGE WATER COMPANY</b>	<b>MONROE (T)</b>			
	Gatehouse restroom	1/23/2018	RT	ABS	1.3
	Gatehouse restroom	2/13/2018	RT	ABS	1.4
	Gatehouse restroom	3/13/2018	RT	ABS	1.5
<b>NY3501333</b>	<b>MAPLE TREE MOBILE HOMES</b>	<b>DEERPARK (T)</b>			
	1 Pleasant Lane kitchen tap	1/22/2018	RT	ABS	0.2
	1 Pleasant Hill kitchen tap	2/20/2018	RT	ABS	1.2
	1 Pleasant Lane kitchen tap	3/26/2018	RT	ABS	
	8 Fox Lane kitchen tap	4/10/2018	RT	ABS	1.6
<b>NY3503533</b>	<b>MAYBROOK VILLAGE</b>	<b>MAYBROOK (V)</b>			
	Stewart's restroom	1/3/2018	RT	ABS	0.9
	Stewart's restroom sink	4/4/2018	RT	ABS	1.5

# Orange County Department of Health Division of Environmental Health

## Coliform samples collected by OCDOH

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>	
<b>NY3515286</b>	<b>MGU REALTY</b>	<b>MONTGOMERY (T)</b>				
	6 Roswin Road side yard tap	3/20/2018	RT	ABS	0.3	
<b>NY3503534</b>	<b>MIDDLETOWN CITY</b>	<b>MIDDLETOWN (C)</b>				
	Thrall Library reading room men's bathroom hand sink	1/2/2018	RT	ABS	1.2	
	Saffron men's bathroom left handsink tap	4/3/2018	RT	ABS	1.4	
<b>NY3503535</b>	<b>MONROE VILLAGE</b>	<b>MONROE (V)</b>				
	25 Park Ave. kitchen tap	1/3/2018	RT	PRES	ABS	0.8
	25 Park Ave. kitchen tap original sampling point	1/8/2018	RP	ABS	0.7	
	Route 208 Mobil restroom sink	1/8/2018	RP	ABS	0.9	
	Shop Rite men's room	1/8/2018	RP	ABS	1.1	
<b>NY3503632</b>	<b>MONROE WD #01 (HIGH RIDGE)</b>	<b>MONROE (T)</b>				
	18 High Ridge Road kitchen sink	1/23/2018	RT	ABS	1.2	
	18 High Ridge Road kitchen sink	1/23/2018	RT	ABS	1.2	
	18 High Ridge kitchen	2/27/2018	RT	ABS	1.3	
	18 High Ridge kitchen	2/27/2018	RT	ABS	1.3	
	18 High Ridge Road kitchen tap	3/27/2018	RT	ABS	1.1	
	18 High Ridge Road kitchen tap	3/27/2018	RT	ABS	1.1	
	High Ridge Road kitchen	4/17/2018	RT	ABS	1	
	High Ridge Road kitchen	4/17/2018	RT	ABS	1	

# Orange County Department of Health Division of Environmental Health

## Coliform samples collected by OCDOH

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>
<b>NY3503633</b>	<b>MONROE WD #02-STERL. MAN., HOR.</b>	<b>MONROE (T)</b>			
	150 Neptune Drive downstairs bathroom	1/8/2018	RT ABS		1.3
	150 Neptune Drive downstairs bathroom	1/8/2018	RT ABS		1.3
	141 Neptune Drive kitchen tap	2/20/2018	RT ABS		0.9
	141 Neptune Drive kitchen tap	2/20/2018	RT ABS		0.9
	Tank building finished water tap	3/13/2018	RT ABS		1.2
	Tank building finished water tap	3/13/2018	RT ABS		1.2
	141 Neptune Drive kitchen	4/4/2018	RT ABS		1.3
	141 Neptune Drive kitchen	4/4/2018	RT ABS		1.3
<b>NY3522546</b>	<b>MONROE WD #07 (ORECO TERRACE)</b>	<b>MONROE (T)</b>			
	55 Oreco Terrace kitchen	1/3/2018	RT ABS		0.2
	55 Oreco Terrace kitchen	1/3/2018	RT ABS		0.2
	49 Oreco Terrace kitchen	2/26/2018	RT ABS		0.9
	49 Oreco Terrace kitchen	2/26/2018	RT ABS		0.9
	25 Oreco Terr.side yard tap	3/27/2018	RT ABS		0.7
	25 Oreco Terr.side yard tap	3/27/2018	RT ABS		0.7
<b>NY3503541</b>	<b>MONROE WD #08 (SKYVIEW HILLS)</b>	<b>MONROE (T)</b>			
	319 Orchard Drive kitchen	1/3/2018	RT ABS		1
	319 Orchard Drive kitchen	1/3/2018	RT ABS		1
	361 Orchard Drive kitchen	2/27/2018	RT ABS		1.4
	361 Orchard Drive kitchen	2/27/2018	RT ABS		1.4
	319 Orchard Drive kitchen	3/12/2018	RT ABS		1.4
	319 Orchard Drive kitchen	3/12/2018	RT ABS		1.4
	319 Orchard Drive kitchen	4/18/2018	RT ABS		1
	319 Orchard Drive kitchen	4/18/2018	RT ABS		1



# Orange County Department of Health Division of Environmental Health

## Coliform samples collected by OCDOH

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>	
<b>NY3530052</b>	<b>MONROE WD #10 - PINE TREE ROAD</b>	<b>MONROE (T)</b>				
	34 Post Road kitchen tap	1/23/2018	RT	ABS	0.8	
	34 Post Road kitchen tap	1/23/2018	RT	ABS	0.8	
	34 Post Road kitchen	2/27/2018	RT	ABS	0.5	
	34 Post Road kitchen	2/27/2018	RT	ABS	0.5	
	34 Post Road kitchen	3/13/2018	RT	ABS	0.7	
	34 Post Road kitchen	3/13/2018	RT	ABS	0.7	
	34 Post Road bathroom	4/18/2018	RT	ABS	0.3	
	34 Post Road bathroom	4/18/2018	RT	ABS	0.3	
<b>NY3503539</b>	<b>MONROE WD #12 (MONROE HILLS ESTATES</b>	<b>MONROE (T)</b>				
	5 Laura Road kitchen	1/23/2018	RT	ABS	0.5	
	5 Laura Road kitchen	1/23/2018	RT	ABS	0.5	
	5 Laura Road kitchen	2/20/2018	RT	ABS	0.9	
	5 Laura Road kitchen	2/20/2018	RT	ABS	0.9	
	Pump house #1 entry point	3/13/2018	RT	ABS	0.9	
	Pump house #1 entry point	3/13/2018	RT	ABS	0.9	
	5 Laura Road kitchen	4/9/2018	RT	ABS	0.8	
	5 Laura Road kitchen	4/9/2018	RT	ABS	0.8	
<b>NY3510480</b>	<b>MONTGOMERY NURSING HOME</b>	<b>MONTGOMERY (T)</b>				
	Lobby restroom	1/10/2018	RT	ABS	1.5	
	North Wing Nursing Station kitchen sink	2/21/2018	RT	ABS	1.1	
	Lobby men's room	3/20/2018	RT	ABS	0.9	
	Kitchen pot wash sink	4/11/2018	RT	ABS	1.2	
<b>NY3503542</b>	<b>MONTGOMERY VILLAGE</b>	<b>MONTGOMERY (V)</b>				
	DPW bathroom sink	2/5/2018	RT	ABS	0.9	

**Orange County Department of Health  
Division of Environmental Health**

**Coliform samples collected by OCDOH**

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>	
<b>NY3512264</b>	<b>MONTGOMERY W.D. #1</b>	<b>MONTGOMERY (T)</b>				
	Speedy Gas men's room	3/12/2018	RT	ABS	1	
	Speedway men's room	4/18/2018	RT	ABS	0.7	
<b>NY3503596</b>	<b>MOUNTAIN LODGE PARK DEVELOPMEN</b>	<b>BLOOMING GROVE (T)</b>				
	2 Garland Trail front yard tap	1/3/2018	RT	ABS	1.4	
	2 Glenwood Road rear yard tap	2/20/2018	RT	ABS	1	
	2 Glenwood Road read yard tap	3/26/2018	RT	ABS	0.7	
	2 Glenwood Road rear yard tap	4/17/2018	RT	ABS	0.8	
<b>NY3501323</b>	<b>MT. ORANGE TRAILER PARK</b>	<b>WAWAYANDA (T)</b>				
	43 Peter Dr. kitchen tap	1/3/2018	RT	ABS	0.2	
	43 Peter Drive kitchen tap	2/26/2018	RT	ABS	3.5	
	43 Peter Drive kitchen tap	3/22/2018	RT	ABS	2.2	
	35 Peter Drive kitchen tap	4/3/2018	RT	ABS	2.8	
<b>NY3503034</b>	<b>N.Y.U. HOUSING</b>	<b>TUXEDO (T)</b>				
	Building #229 side yard tap	1/16/2018	RT	ABS	0.5	
	Building #229 side yard tap	2/6/2018	RT	ABS	0.3	
	Building #229 side yard tap	3/6/2018	RT	ABS	0.5	
	229 Ironwood Drive side yard tap	4/10/2018	RT	ABS	0.5	
<b>NY3513656</b>	<b>NEW HAMPTON TRAILER PARK</b>	<b>WAWAYANDA (T)</b>				
	37 Katherine Lane kitchen tap	3/22/2018	RT	ABS	0.4	

**Orange County Department of Health  
Division of Environmental Health**

**Coliform samples collected by OCDOH**

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>	
<b>NY3503607</b>	<b>NEW VERNON ESTATES</b>	<b>MOUNT HOPE (T)</b>				
	104 Witte Dr. kitchen tap	1/23/2018	RT	ABS	0.7	
	104 Witte Dr. kitchen tap	1/23/2018	RT	ABS	0.7	
	104 Witte Drive kitchen tap	2/21/2018	RT	ABS	1.8	
	104 Witte Drive kitchen tap	2/21/2018	RT	ABS	1.8	
	58 Witte Drive kitchen tap	3/19/2018	RT	ABS	0.5	
	58 Witte Drive kitchen tap	3/19/2018	RT	ABS	0.5	
	104 Witte Drive kitchen tap	4/11/2018	RT	ABS	0.5	
	104 Witte Drive kitchen tap	4/11/2018	RT	ABS	0.5	
<b>NY3503580</b>	<b>NEW WINDSOR CONSOLIDATED WD</b>	<b>NEW WINDSOR (T)</b>				
	Vails Gate McDonald's men's restroom	1/16/2018	RT	ABS	1.3	
	McDonald's men's room	4/16/2018	RT	ABS	1.2	
<b>NY3503549</b>	<b>NEWBURGH CITY</b>	<b>NEWBURGH (C)</b>				
	Broadway Dunkin Donuts men's room	3/20/2018	RT	ABS	1.5	
<b>NY3503578</b>	<b>NEWBURGH CONSOLIDATED WD</b>	<b>NEWBURGH (T)</b>				
	Speedway men's room	1/10/2018	RT	ABS	0.7	
<b>NY3530149</b>	<b>O.C. CORRECTIONAL FACILITY</b>	<b>GOSHEN (T)</b>				
	Sheriff's Administration men's bathroom hand sink tap	1/8/2018	RT	ABS	0.2	
	Sheriff's Office Main Lobby men's bathroom right hand	2/6/2018	RT	ABS	0.1	
	Sheriff's Office main lobby men's bathroom left hand si	3/20/2018	RT	ABS	0.2	
	Sheriff's Office main lobby men's bathroom left handsi	4/3/2018	RT	ABS	0.2	

# Orange County Department of Health Division of Environmental Health

## Coliform samples collected by OCDOH

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>	
<b>NY3519648</b>	<b>ORANGE COUNTY ESTATES, INC</b>	<b>CRAWFORD (T)</b>				
	Lot #11 kitchen sink	1/2/2018	RT	ABS	0.9	
	Lot #11 kitchen	2/5/2018	RT	ABS	0.7	
	Lot #11 kitchen sink	3/5/2018	RT	ABS	0.9	
	Lot #11 kitchen sink	4/3/2018	RT	ABS	0.6	
<b>NY3513621</b>	<b>ORANGE LAKE TRAILER PARK</b>	<b>MONTGOMERY (T)</b>				
	Lot #224 kitchen sink	1/10/2018	RT	ABS	0.3	
	Lot #244 kitchen	2/21/2018	RT	ABS	1.5	
	Lot #243 side yard tap	3/20/2018	RT	ABS	1.6	
	Lot #243 side yard tap	4/11/2018	RT	ABS	0.5	
<b>NY3503552</b>	<b>OTISVILLE VILLAGE</b>	<b>OTISVILLE (V)</b>				
	Grogan's Pub men's bathroom hand sink tap	1/3/2018	RT	ABS	1.6	
	Otisville Mart Deli hand sin tap	4/2/2018	RT	ABS	1.6	
<b>NY3503621</b>	<b>PAINTED APRON WATER CO, T.O.</b>	<b>DEERPARK (T)</b>				
	240 Neversink Drive kitchen tap	2/13/2018	RT	ABS	2	
	240 Neversink Drive kitchen tap	3/5/2018	RT	ABS	1.8	
	240 Neversink Drive kitchen tap	4/2/2018	RT	ABS	2.2	
<b>NY3505660</b>	<b>PHEASANT HILL</b>	<b>MINISINK (T)</b>				
	35 The Place outside tap	1/10/2018	RT	ABS	0.735	
	35 The Place outside tap	2/6/2018	RT	ABS	0.7	
	35 The Place outside tap	3/5/2018	RT	ABS	1.8	
	35 The Place outside tap	4/3/2018	RT	ABS	1.2	

**Orange County Department of Health  
Division of Environmental Health**

**Coliform samples collected by OCDOH**

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>
<b>NY3503553</b>	<b>PINE BUSH WATER DISTRICT</b>	<b>CRAWFORD (T)</b>			
	McDonald's men's room	1/2/2018	RT	ABS	1
	McDonald's men's room	4/3/2018	RT	ABS	0.7
<b>NY3501320</b>	<b>PINE GROVE MOBILE HOME PARK</b>	<b>DEERPARK (T)</b>			
	708 Mockingbird Lane bathroom handsink tap	1/22/2018	RT	ABS	0.7
	714 Mockingbird Lane bathroom handsink tap	2/20/2018	RT	ABS	0.3
	Treatment building entry point tap	3/12/2018	RT	ABS	0.7
	714 Mockingbird Lane bathroom handsink tap	4/10/2018	RT	ABS	0.5
<b>NY3503590</b>	<b>PINE ISLAND WATER CO.</b>	<b>WARWICK (T)</b>			
	Treatment building utility sink tap	1/2/2018	RT	ABS	0.2
	Treatment building utility sink tap	2/6/2018	RT	ABS	0.2
	Treatment building entry point tap	3/6/2018	RT	ABS	0.3
	590 Glenwood Road outside tap	4/9/2018	RT	ABS	0.2
<b>NY3503554</b>	<b>PORT JERVIS CITY</b>	<b>PORT JERVIS (C)</b>			
	Bagel Station men's bathroom hand sink tap	1/8/2018	RT	ABS	0.9
	Municipal Building basement men's bathroom handsin	4/2/2018	RT	ABS	0.7
<b>NY3520890</b>	<b>REDWOOD PROPERTIES LLC</b>	<b>WALLKILL (T)</b>			
	Apt. #10 kitchen tap	3/19/2018	RT	ABS	0.7
<b>NY3503626</b>	<b>RIDGEBURY LAKE ACRES</b>	<b>WAWAYANDA (T)</b>			
	64 View Point Drive outside tap	1/10/2018	RT	ABS	1.8
	64 View Point Drive outside tap	2/14/2018	RT	ABS	1.6
	64 View Point Drive outside tap	3/5/2018	RT	ABS	2.2
	64 View Point Drive outside tap	4/3/2018	RT	ABS	1.2

**Orange County Department of Health  
Division of Environmental Health**

**Coliform samples collected by OCDOH**

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>	
<b>NY3516857</b>	<b>ROBINN MEADOWS</b>	<b>WAWAYANDA (T)</b>				
	23 Maureen Drive kitchen tap	1/16/2018	RT	ABS	2.8	
	Robinn Drive kitchen tap	2/14/2018	RT	ABS	2.5	
	20 Robinn Drive kitchen tap	3/22/2018	RT	ABS	2.6	
	23 Maureen kitchen	4/10/2018	RT	ABS	1.6	
<b>NY3510766</b>	<b>ROCK TERRACE TRAILER PARK</b>	<b>HIGHLANDS (T)</b>				
	Lot #71 bathroom	1/9/2018	RT	ABS	0.4	
	Lot #8 kitchen	2/14/2018	RT	ABS	0.4	
	Well house #3 side tap	3/26/2018	RT	ABS	0.6	
	Lot #14 kitchen	4/16/2018	RT	ABS	0.5	
<b>NY3503565</b>	<b>RURAL ATLANTIC WATER CO.</b>	<b>WARWICK (T)</b>				
	Treatment building entry point tap	1/2/2018	RT	ABS	1.2	
	Treatment building entry point tap	1/2/2018	RT	ABS	1.2	
	Treatment building entry point tap	2/6/2018	RT	ABS	2.2	
	Treatment building entry point tap	2/6/2018	RT	ABS	2.2	
	Treatment building entry point tap	3/6/2018	RT	ABS	1.8	
	Treatment building entry point tap	3/6/2018	RT	ABS	1.8	
	Treatment room entry point tap	4/9/2018	RT	ABS	1.8	
	Treatment room entry point tap	4/9/2018	RT	ABS	1.8	

**Orange County Department of Health  
Division of Environmental Health**

**Coliform samples collected by OCDOH**

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>
<b>NY3503574</b>	<b>RURAL RIDGE WATER DIST.</b>	<b>HAMPTONBURGH (T)</b>			
	44 Hickory Drive kitchen tap	1/8/2018	RT	ABS	0.7
	44 Hickory Drive kitchen tap	1/8/2018	RT	ABS	0.7
	44 Hickory Drive kitchen tap	1/8/2018	RT	ABS	0.7
	3 Hickory Drive foyer bathroom	2/20/2018	RT	ABS	0.4
	3 Hickory Drive foyer bathroom	2/20/2018	RT	ABS	0.4
	3 Hickory Drive foyer bathroom	2/20/2018	RT	ABS	0.4
	3 Hickory Drive foyer bathroom	3/19/2018	RT	ABS	0.3
	3 Hickory Drive foyer bathroom	3/19/2018	RT	ABS	0.3
	3 Hickory Drive foyer bathroom	3/19/2018	RT	ABS	0.3
	Treatment building finished water tap	4/4/2018	RT	ABS	0.7
	Treatment building finished water tap	4/4/2018	RT	ABS	0.7
	Treatment building finished water tap	4/4/2018	RT	ABS	0.7
<b>NY3503587</b>	<b>SCHILLER WATER SUPPLY</b>	<b>MONROE (T)</b>			
	17 Ludlam Road front yard tap	2/20/2018	RT	ABS	
	17 Ludlam Road front yard tap	4/4/2018	RT	ABS	
<b>NY3503555</b>	<b>SCOTCHTOWN PARK</b>	<b>GOSHEN (T)</b>			
	32 Ruby Lane kitchen tap	1/23/2018	RT	ABS	0.3
	30 Ruby Lane outside tap	2/26/2018	RT	ABS	0.2
	32 Ruby Lane kitchen tap	3/19/2018	RT	ABS	0.7
	32 Ruby Lane kitchen tap	4/4/2018	RT	ABS	0.2

# Orange County Department of Health Division of Environmental Health

## Coliform samples collected by OCDOH

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>	
<b>NY3503600</b>	<b>SCOTT ACRES</b>	<b>NEW WINDSOR (T)</b>				
	10 Glen Round bathroom tap	1/2/2018	RT	ABS	1	
	13 Glen Round kitchen sink	2/14/2018	RT	ABS	0.5	
	Well house finished water tap	3/14/2018	RT	ABS	0.7	
	10 Glen Round bathroom tap	4/3/2018	RT	ABS	0.5	
<b>NY3530204</b>	<b>SERGIO LANE</b>	<b>MONROE (T)</b>				
	12 Sergio Lane kitchen	2/13/2018	RT	ABS		
<b>NY3530231</b>	<b>SISTERS OF THE PRESENTATION OF THE B</b>	<b>NEW WINDSOR (T)</b>				
	Kitchen hand wash sink	1/9/2018	RT	ABS	3	
	Kitchen hand wash sink	2/21/2018	RT	ABS	1.5	
	Kitchen hand wash sink	3/26/2018	RT	ABS	1.7	
	Kitchen hand wash	4/10/2018	RT	ABS	1.8	
<b>NY3503569</b>	<b>SLATE HILL (GREEN)</b>	<b>WAWAYANDA (T)</b>				
	Body Shop utility sink tap	1/2/2018	RT	ABS	0.9	
	Body shop utility sink tap	2/6/2018	RT	ABS	0.7	
	Green's body shop utility sink tap	3/6/2018	RT	ABS	0.7	
	Body Shop utility sink tap	4/2/2018	RT	ABS	2.2	
<b>NY3510681</b>	<b>SLEEPY HOLLOW MOBILE PARK</b>	<b>MONTGOMERY (T)</b>				
	593 Hatter Lane kitchen	1/9/2018	RT	PRES	ABS	0.2
	543 Copperfield Lane kitchen	2/6/2018	RT	ABS		0.3
	600 Hatter Lane kitchen tap	3/6/2018	RT	ABS		0.4
	600 Hatter Lane kitchen sink	4/10/2018	RT	ABS		0.8
<b>NY3510641</b>	<b>SOUTH BLOOMING GROVE VILLAGE WD 1</b>	<b>BLOOMING GROVE (T)</b>				
	Cookoo's Nest men's room	1/22/2018	RT	ABS		1.5



# Orange County Department of Health Division of Environmental Health

## Coliform samples collected by OCDOH

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>
<b>NY3501334</b>	<b>SOUTH MAPLE ESTATES</b>		<b>DEERPARK (T)</b>		
	Butler's basement 2 bay utility sink tap	2/26/2018	RT	ABS	0.3
	Butler's basement 2 bay utility sink tap	4/2/2018	RT	ABS	0.3
<b>NY3530033</b>	<b>SPUR TERRACE APARTMENTS</b>		<b>WARWICK (T)</b>		
	Treatment room entry point tap	3/6/2018	RT	ABS	0.7
	Apt. #36 kitchen tap	4/9/2018	RT	ABS	0.7
<b>NY3512133</b>	<b>STERLING LAKE</b>		<b>WARWICK (T)</b>		
	NYU Medical Center boiler room sink	1/16/2018	RT	ABS	1.5
	NYU Medical Center basement men's room	2/6/2018	RT	ABS	0.5
	NYU Med Ctr downstairs men's room	3/6/2018	RT	ABS	0.7
	NYU Med Research Center downstairs men's room	4/10/2018	RT	ABS	0.4
<b>NY3503614</b>	<b>STONE HEDGE</b>		<b>GOSHEN (T)</b>		
	11 Lark Terr. outside tap	1/10/2018	RT	ABS	0.2
	11 Lark Terr. bathroom handsink tap	2/14/2018	RT	ABS	0.2
	11 Lark Terr. bathroom handdisk tap	3/6/2018	RT	ABS	0.1
	4 Partridge Lane laundry room utility sink tap	4/17/2018	RT	ABS	0.2
<b>NY3501328</b>	<b>STONY FORD PARK</b>		<b>WALLKILL (T)</b>		
	136 Casimer kitchen tap	3/13/2018	RT	ABS	1.4
<b>NY3503576</b>	<b>SUGAR LOAF HILLS</b>		<b>CHESTER (T)</b>		
	Ross Realty bathroom handsink tap	1/16/2018	RT	ABS	0.5
	A.J. Ross Marketing bathroom handsink tap	2/6/2018	RT	ABS	0.7
	CJ Ross Creative Media bathroom handsink tap	3/6/2018	RT	ABS	0.7
	A.J. Ross Marketing & Design bathroom handsink tap	4/11/2018	RT	ABS	0.7

**Orange County Department of Health  
Division of Environmental Health**

**Coliform samples collected by OCDOH**

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>	
<b>NY3503582</b>	<b>SURREY MEADOW W.D.</b>	<b>CHESTER (T)</b>				
	52 Surrey Road outside tap	1/10/2018	RT	ABS	0.7	
	52 Surrey Road outside tap	2/6/2018	RT	ABS	0.9	
	52 Surrey Road outside tap	3/5/2018	RT	ABS	0.7	
	52 Surrey Road outside tap	4/4/2018	RT	ABS	0.7	
<b>NY3518454</b>	<b>SY208 MANAGEMENT, LLC</b>	<b>BLOOMING GROVE (T)</b>				
	Mechanical Room 1st entry point	1/22/2018	RT	ABS	1.5	
	Mechanical Room 1st entry point	1/22/2018	RT	ABS	1.5	
	Apt. #13 kitchen	4/9/2018	RT	ABS	0.3	
	Apt. #13 kitchen	4/9/2018	RT	ABS	0.3	
<b>NY3510560</b>	<b>TUXEDO HEIGHTS CONDO ASSOC.</b>	<b>TUXEDO (T)</b>				
	Office sink	1/16/2018	RT	PRES	ABS	
	Office sink	2/6/2018	RT	ABS	1.4	
	Apt. 1106 kitchen	3/6/2018	RT	ABS	1	
	Office sink	4/10/2018	RT	ABS	1	
<b>NY3503557</b>	<b>TUXEDO PARK VILLAGE</b>	<b>TUXEDO PARK (V)</b>				
	Orange Top Inn men's room	3/6/2018	RT	ABS	1	
	Library 1st floor restroom	4/10/2018	RT	ABS	1	
<b>NY3511887</b>	<b>U.S.M.A. - LUSK SYSTEM</b>	<b>HIGHLANDS (T)</b>				
	Fitness Center men's room	1/9/2018	RT	ABS	1.4	
	Fitness Center men's room	4/16/2018	RT	ABS	0.7	
<b>NY3511338</b>	<b>U.S.M.A. - STONEY LONESOME SYS</b>	<b>HIGHLANDS (T)</b>				
	PX Exchange men's room	1/9/2018	RT	ABS	0.8	
	Express men's room	4/16/2018	RT	ABS	1	

# Orange County Department of Health Division of Environmental Health

## Coliform samples collected by OCDOH

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>	
<b>NY3503558</b>	<b>UNIONVILLE VILLAGE</b>	<b>UNIONVILLE (V)</b>				
	Village Office bathroom handsink tap	1/2/2018	RT	ABS	0.7	
	Village Office bathroom handsink tap	2/6/2018	RT	ABS	0.7	
	Village Office bathroom handsink tap	3/6/2018	RT	ABS	2.5	
	Village Office bathroom handsink tap	4/2/2018	RT	ABS	0.7	
<b>NY3510449</b>	<b>VALLEY VIEW CTR FOR NURSING CARE &amp; R</b>	<b>GOSHEN (T)</b>				
	Town Center utility sink tap	1/10/2018	RT	ABS	0.3	
	Town Center stainless steel sink tap	2/21/2018	RT	ABS	0.3	
	Town Center stainless steel sink tap	3/13/2018	RT	ABS	0.3	
	Town Center concession stainless steel sink tap	4/4/2018	RT	ABS	0.3	
<b>NY3501315</b>	<b>VALLEY VIEW PARK</b>	<b>WALLKILL (T)</b>				
	504 5th Ave. kitchen tap	1/3/2018	RT	ABS	0.5	
	507 5th Ave. kitchen tap	2/13/2018	RT	ABS	0.7	
	507 5th Avenue kitchen tap	3/19/2018	RT	ABS	0.9	
	507 5th Ave. kitchen tap	4/3/2018	RT	ABS	5	
<b>NY3513627</b>	<b>VALLEY VIEW WEST</b>	<b>WALLKILL (T)</b>				
	11 Hidden Valley Dr. kitchen tap	1/3/2018	RT	ABS	1.2	
	24 Hidden Valley Drive kitchen tap	1/3/2018	RT	ABS	0.3	
	24 Hidden Valley Dr. kitchen tap	2/13/2018	RT	ABS	0.3	
	11 Hidden Valley Dr. kitchen tap	2/13/2018	RT	ABS	1.2	
	24 Hidden Valley Drive kitchen tap	3/19/2018	RT	ABS	0.3	
	13 Hidden Valley Drive kitchen tap	3/19/2018	RT	ABS	1.2	
	11 Hidden Valley Drive kitchen tap	4/3/2018	RT	ABS	1.6	
	32 Hidden Valley Drive kitchen tap	4/3/2018	RT	ABS	0.2	

**Orange County Department of Health  
Division of Environmental Health**

**Coliform samples collected by OCDOH**

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>
<b>NY3503559</b>	<b>WALDEN VILLAGE</b>	<b>WALDEN (V)</b>			
	Stewarts restroom tap	1/10/2018	RT	ABS	1.1
	Stewarts restroom	4/11/2018	RT	ABS	1.1
<b>NY3503584</b>	<b>WALLKILL CONSOLIDATED WD</b>	<b>WALLKILL (T)</b>			
	Scotchtown Laundromat bathroom handsink tap	3/19/2018	RT	ABS	0.5
<b>NY3503586</b>	<b>WALLKILL HEIGHTS</b>	<b>WALLKILL (T)</b>			
	15 Pennsylvania Ave. outside tap	1/22/2018	RT	ABS	0.5
	California Drive kitchen tap	2/13/2018	RT	ABS	0.7
	29 California Drive kitchen tap	3/26/2018	RT	ABS	0.7
	23 California Drive kitchen tap	4/10/2018	RT	ABS	0.7
<b>NY3501317</b>	<b>WALTERS MOBILE HOME VILLAGE</b>	<b>NEW WINDSOR (T)</b>			
	Office kitchen tap	1/2/2018	RT	ABS	1.4
	Office kitchen sink	2/5/2018	RT	ABS	1.4
	Office kitchen	3/5/2018	RT	ABS	1.1
	Office kitchen tap	4/3/2018	RT	ABS	1.2
<b>NY3503525</b>	<b>WALTON LAKE ESTATES W.D.</b>	<b>CHESTER (T)</b>			
	15 Poplar Drive bathroom handsink tap	1/16/2018	RT	ABS	1.2
	27 Maple Lane kitchen tap	2/6/2018	RT	ABS	1.2
	15 Poplar Drive bathroom handsink tap	3/20/2018	RT	ABS	0.7
	27 Maple kitchen	4/9/2018	RT	ABS	0.7
<b>NY3510138</b>	<b>WARWICK RIDGE APARTMENTS</b>	<b>WARWICK (T)</b>			
	Laundry room utility sink tap	1/10/2018	RT	ABS	0.7
	Laundry room utility sink tap	4/4/2018	RT	ABS	0.2

**Orange County Department of Health  
Division of Environmental Health**

**Coliform samples collected by OCDOH**

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>
<b>NY3503561</b>	<b>WARWICK VILLAGE</b>	<b>WARWICK (V)</b>			
	Village Building bathroom hand sink tap	1/2/2018	RT	ABS	1.6
	Village Building bathroom handsink tap	4/4/2018	RT	ABS	2.2
<b>NY3503567</b>	<b>WASHINGTONVILLE VILLAGE</b>	<b>WASHINGTONVILLE (V)</b>			
	Stewarts restroom tap	2/13/2018	RT	ABS	1
<b>NY3530066</b>	<b>WAWAYANDA WD#1</b>	<b>WAWAYANDA (T)</b>			
	Valvoline bathroom hand sink tap	1/2/2018	RT	ABS	0.9
	Valvoline bathroom handsink tap	2/14/2018	RT	ABS	1.2
	Valvoline bathroom handsink tap	3/14/2018	RT	ABS	1.4
	Valvoline bathroom handsink tap	4/4/2018	RT	ABS	1.2
<b>NY3503566</b>	<b>WESTSIDE GREENWOOD LAKE W.D.</b>	<b>WARWICK (T)</b>			
	Treatment building utility sink tap	1/16/2018	RT	ABS	3.5
<b>NY3521087</b>	<b>WESTTOWN ASSOCIATES</b>	<b>MINISINK (T)</b>			
	North - Laundry room tap	3/6/2018	RT	ABS	0.3
	South - treatment room entry point tap	3/6/2018	RT	ABS	2.8
	Treatment room entry point tap	4/3/2018	RT	ABS	3.2
	Laundry room tap	4/3/2018	RT	ABS	0.3

# Orange County Department of Health Division of Environmental Health

## Coliform samples collected by OCDOH

Note: Samples are analyzed by Aquatech Labs (ID#10673)

\*To search use the Search button at the top of the page and type in your Fed ID#\*

<u>Fed ID#</u>	<u>PWS Name and Sampling Location</u>	<u>Date</u>	<u>T.Coliform</u>	<u>E.Coli</u>	<u>CL Residual (mg/l)</u>	
<b>NY3503611</b>	<b>WHITLOCK FARMS</b>	<b>MOUNT HOPE (T)</b>				
	19 Sagamore Drive outside tap	1/23/2018	RT PRES	ABS		
	19 Sagamore Drive outside tap	1/23/2018	RT PRES	ABS		
	1 Sagamore Drive bathroom left handsink tap	2/20/2018	RT	ABS		
	1 Sagamore Drive bathroom left handsink tap	2/20/2018	RT	ABS		
	14 Sagamore Drive kitchen tap	3/26/2018	RT	ABS	0.5	
	14 Sagamore Drive kitchen tap	3/26/2018	RT	ABS	0.5	
	14 Sagamore Drive kitchen tap	4/11/2018	RT	ABS	0.5	
	14 Sagamore Drive kitchen tap	4/11/2018	RT	ABS	0.5	
<b>NY3505663</b>	<b>WICKHAM VILLAGE</b>	<b>WARWICK (T)</b>				
	8 Wickham Drive kitchen tap	3/20/2018	RT	ABS	1.5	
<b>NY3503573</b>	<b>WOODBURY CONS. W.D.</b>	<b>WOODBURY (T)</b>				
	Rushmore Library branch men's room	2/6/2018	RT	ABS	0.3	
<b>NY3503570</b>	<b>WOODBURY W.D. #6 (AMDUR PARK)</b>	<b>WOODBURY (T)</b>				
	17 1st Avenue kitchen	1/22/2018	RT	ABS	0.2	
	17 1st Avenue kitchen	2/26/2018	RT	ABS	0.2	
<b>NY3503547</b>	<b>WOODLAND DRIVE HOMEOWNERS ASSO</b>	<b>NEWBURGH (T)</b>				
	Surveillance tap	1/10/2018	RT	ABS	0.3	
	Surveillance tap	2/21/2018	RT	ABS	0.4	
	Surveillance tap	3/20/2018	RT	ABS	0.2	
	Surveillance tap	4/11/2018	RT	ABS	0.3	